



#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re the application of

Group Art Unit 2653

Hardayal S. Gill

Examiner: Christopher R. Magee

Serial No.: 10/081,046

Docket No. SJO920010142US1

Title: Magnetoresistance Sensor Having an Antiferromagnetic Pinning Layer with Both

Surfaces Pinning Ferromagnetic Bias Layers

U. S. Patent 6,961,225 B2

Issued:

November 1, 2005

#### LETTER REQUESTING CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate

JAN 3 1 2006

of Correction

Dear Sir:

Corrections that are necessary for this patent are listed on the attached "Certificate of Correction". If applicable, the Commissioner is hereby authorized to charge payment of any fees associated with this Certificate of Correction to Deposit Account 09-0466. A duplicate of this sheet is attached.

Respectfully submitted,

Abdy Raissinia (Reg. No. 38,686)

Attorney for Applicants

IBM Corporation, (L2PA/J2C)

650 Harry Road

San Jose, CA 95120

(408) 927-3388



### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re the application of

Group Art Unit 2653

Hardayal S. Gill

Examiner: Christopher R. Magee

Serial No.: 10/081,046

Docket No. SJO920010142US1

Title: Magnetoresistance Sensor Having an Antiferromagnetic Pinning Layer with Both

Surfaces Pinning Ferromagnetic Bias Layers

U. S. Patent 6,961,225 B2

Issued:

November 1, 2005

## LETTER REQUESTING CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Corrections that are necessary for this patent are listed on the attached "Certificate of Correction". If applicable, the Commissioner is hereby authorized to charge payment of any fees associated with this Certificate of Correction to Deposit Account 09-0466. A duplicate of this sheet is attached.

Respectfully submitted,

Abdy Raissinia (Reg. No. 38,686)

Attorney for Applicants

IBM Corporation, (L2PA/J2C)

650 Harry Road San Jose, CA 95120 (408) 927-3388 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

		Dago 1	of 1
PATENT NO. : 6,	,961,225 BZ	Page1_	01
APPLICATION NO.: 10	0/081,046		
ISSUE DATE : N	lovember 1, 2005		
INVENTOR(S) : H	lardayal Singh Gill		
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:			
Column 8, line 24, after "antiferromagnetic", insertlayer			
Column 8, line 40, after "antiferromagnetic", insertlayer			

MAILING ADDRESS OF SENDER (Please do not use customer number below):

IBM Corporation 650 Harry Road (L2PA/J2C) San Jose, CA 95120

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.